

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20161179, Building Permit - Commercial Address: 1820 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rough Framing Inspection - Commercial	John Borns	Partial	Friday, May 05, 2017
Partial Correction 1 Misc		COVER EXTERIOR WALL SI ECTING TO ADJACENT STRI	HEATHING AT LINK.AT EAST END JCTURES
Rated Assembly Inspection	John Borns	Partial	Friday, May 05, 2017
Partial Correction 1 Misc	ОК ТО	TAPE, MUD AND FIRE-STC	P WALLS AT B118 & B119

Comments: