PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161756, Building Permit - Commercial Address: 795 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rough Framing John Borns Partial Friday, May 12, 2017

Inspection - Commercial

Partial Correction

1 Misc COMPONENTS OF PORTAL FRAMING: INTERIOR PORTAL STRAPS

IN PLACE AND FULLY NAILED;

Corrective Action Required

3 Misc 1ST FLOOR: CHECK ENTIRE PERIMETER SILL PLATE AND ENSURE

ALL ANCHOR BOLTS ARE INSTALLED PER IBC: MIN TWO PER PIECE; ONE WITHIN 12" OF EACH END OF EACH PIECE; MAX 4'

O/C.

Corrective Action Required

4 Misc 1ST FLOOR: NUMBER OF JACK STUDS SUPPORTING HEADERS IS

NOT IBC COMPLIANT.

Comments: