
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20161624, Building Permit - Residential

Address: 3349 SW JESSIE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Sidewalk Inspection	Brice Lawson	Passed	Tuesday, May 23, 2017

Informational

1 Brice Lawson 05/23/2017 2:48 PM
The 5' sidewalk has been installed and passed inspection. It appears that the white curing compound was not applied to the sidewalk. I informed Bill Kenny that this is a requirement on new driveways and sidewalks.

Informational

1 Brice Lawson 05/17/2017 2:52 PM
The sidewalk forms have been set at less than 2% cross slope. The rock has been compacted.

Occupancy Inspection - Codes	Mike Copeland	Failed	Tuesday, May 23, 2017
Residential			

Corrective Action Required

1	1.	Final grade, sod.
	2.	Garage to be self closing.
	3.	Install 4 three inch screws rear door at the strike side and 2 per hinge.
	4.	Basement bath GFCI not re setting.
	5.	Secure SE cable within 12" of the panel.
	6.	Anchor columns in basement.
	7.	Obtain final sidewalk approval.

Comments:

