

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRRES20162560

Address: 1332 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

Inspected On: Thursday, June 01, 2017

Inspected By: Khanh Nguyen 6/30/2017 **Expiration Date:**

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection -Khanh Nguyen Temporary C of O Thursday, June 01, 2017

Codes Residential

Corrective Action Required:

1 Misc 3. Final grade; erosion control; splashblocks.

6. Install four (4) 3-inch security screws through metal jamb-plate at

downstairs entry door.

**Install a security strike plate