## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRRES20163192, Building Permit - Residential Address: 1329 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday, June 07, 2017

Residential

Corrective Action Required

1 Misc -INSTALL STEEL COLUMNS AS CALLED FOR ON PLAN FOR THE

STEEL BEAM SPANNING BETWEEN FOYER&DINING AND THE

LIVING RM

-COMPLETE GARAGE SOFFIT AND FIREBLOCK AS REQUIRED

\*\*PAN OFF THE RA SPACE FROM SOFFIT

-AT GARAGE WALL&CEILING RETURN AIR SPACE, PROVIDE R-15

THERMAL ENVELOP AT WALL AND R-19 AT CEILING

\*\*PROVIDE SPACE TO ALLOW R-15 INSULATION AT WALL AND

R-19 AT CEILING. PAN OFF RA SPACE FROM INSULATION

-HAVE THE ENGINEER ADDRESS THE FULL SUPPORT FOR THE I BEAM THAT SPANS FROM EAST SIDE OF HOUSE TO CORNER OF

**DUCT CHASE** 

\*\*PLAN ALSO CALLS FOR STEEL COLUMN SUPPORT

\*\*CURRENT STUDS SUPPORT ONLY SUPPORT THE I BEAM ON THE

SIDE, NOT AT THE MIDDLE OR FULL WIDTH

\*\*\*OK TO INSULATE

Comments: