PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161756, Building Permit - Commercial Address: 795 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Rated Assembly Inspection	John Borns	Partial	Monday, July 17, 2017	
Partial Correction 1 Misc		RATED ASSEMBLY AT STAIRWELLS: OK TO COVER 5/8" TYPE X MOLD TOUGH GWB AT NORTH STAIRWELL WALLS: 2ND LAYER AT 1ST LEVEL WELL FACE + 1ST LAYER PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 2ND LEVEL WELL FACE; 2ND LAYER AT 2ND LEVEL WELL FACE + PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 3RD LEVEL WELL FACE; PRE-ROCK AT JOIST SPACE AT BACKSIDE AT 1ST, 2ND & 3RD FLOORS; 1ST LAYER AT 4TH FLOOR;		
Partial Correction 2 Misc		1ST LAYER PRE-ROCK AT JO 2ND LEVEL WELL FACE; 2N PRE-ROCK AT JOIST SPACE WELL FACE + PRE-ROCK A AT 4TH FLOOR;	: 2ND LAYER AT 1ST LEVEL WELL FACE DIST SPACE AT BACKSIDE; 1ST LAYER A D LAYER AT 2ND LEVEL WELL FACE + AT BACKSIDE; 1ST LAYER AT 3RD LEVE JOIST SPACE AT BACKSIDE; 1ST LAYER	
2 IVISC		SHAFT:	ETER PRE-ROCK AT JOIST SPACE AT 1ST	
Partial Correction		5/8" TYPE X GWB AT WEL 1ST FLOORS	L FACE: 1ST LAYER AT 4TH, 3RD, 2ND,	
3 Misc		OK TO COVER AT RATED C		
		1ST FLOOR: 1ST LAYER 5/8	" TYPE X GWB;	

Corrective Action Required 4 Misc

VERTICAL FIRE-BLOCKING AT 10' HORIZ INTERVALS: CLOSE GAPS AT MID-HEIGHT AND TOP OF ALL

All Rough Inspection - Commercial	John Borns	Partial	Monday, July 17, 2017
Partial Correction 2 Misc		OK TO PRE-ROCK WH RD FLOOR;	EN READY AT SHOWERS AT: 4TH FLOOR;

Comments: