## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20161761, Building Permit - Commercial Address: 805 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                  | Inspector: | С  | Outcome:   | Date:   |
|------------------------------|------------|--|--|---|
| Rated Assembly<br>Inspection | John Borns | Ρ  | Partial  | Thursday, July 20, 2017   |
| Partial Correction<br>1 Misc |            | OK TO COVER COMPONENTS OF RATED ASSEMBLIES AT<br>STAIRWELLS:<br>SOUTH STAIRWELL:<br>BASEMENT: 1ST & 2ND LAYER 5/8" TYPE X MOLD-TOUG<br>INCLUDING PRE-ROCK BACKSIDE JOIST BAYS;<br>FIRST FLOOR 1ST LAYER @ WELL FACE + PRE-ROCK AT BA<br>JOIST BAYS; 2ND LAYER PRE-ROCK AT BACKSIDE JOIST B<br>[SECOND FLOOR 1ST LAYER @ WELL FACE + PRE-ROCK A<br>BACKSIDE JOIST BAYS; |  | " TYPE X MOLD-TOUGH GWB<br>IOIST BAYS;<br>ACE + PRE-ROCK AT BACKSIDE<br>( AT BACKSIDE JOIST BAYS; |
| Partial Correction<br>2 Misc |            | FIRST FLO<br>JOIST BA<br>[SECONE<br>BACKSID<br>RATED A<br>BASEME<br>BAYS   | YS; 2ND LAYER PRE-ROCK<br><b>O FLOOR 1ST LAYER @ WI</b><br><b>DE JOIST BAYS;</b><br>SSEMBLIES AT ELEVATOR<br>NT: 1ST & 2ND LAYERS PR |   |

BAYS

[SECOND FLOOR 1ST LAYER PRE-ROCK AT BACKSIDE JOIST BAYS;

Comments: