

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRRES20171327, Building Permit - Residential
Address: 1816 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mark Harding	Failed	Tuesday, August 15, 2017

Corrective Action Required

1	Misc	secure wardflex where required, mstr fireplace, 1st floor fireplace, attic. - complete electrical to fireplaces. - firestop garage wall chase and heat chase vertical to horizontal. - install all joist hangers where required 1st floor. installed hangers missing nails. - support flex ducts in attic per code. - valley leg on no bearing mstr east wall. - support all dwv. - missing beam posts in bsmt see plans.
---	------	---

Electrical Service Inspection - Residential	Mark Harding	Passed	Tuesday, August 15, 2017
--	--------------	--------	--------------------------

Corrective Action Required

1

Erosion Control	Mark Harding	Failed	Tuesday, August 15, 2017
------------------------	--------------	--------	--------------------------

Comments: