

## Inspection Summary

Permit #: PRCOM20161180, Building Permit - Commercial

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK AVE, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	John Borns	Partial	Friday, September 01, 2017
Partial Correction 1 Misc		OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT CEILING AND WALLS AT: LINK CORRIDOR A111 SOUTH 36' + "B"-TO-COMMONS LINK; CORR 205 WALLS + LID; CORR A-305 LID & WALLS; [CORR 405;  UNITS 203; 204; 232; 233;	
Partial Correction 2 Misc		OK TO TAPE, MUD, AND FIRE-STOP PRE-ROCK AT SHOWERS/TUBS AT: 203; 204; 232; 233; 303; 304; 332; 333; 403; 404; 432; 433; 201; 234; 301; 334; 401; 434; <b>[201; 234;</b>	
Partial Correction 3 Misc		OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB ABOVE CEILING AT BACKSIDE OF STAIRWELLS AT: 203; 204; 232; 303; 304; 332; 333; 403; 404; 432; 433; 303; 304; 332;	
<b>All Rough Inspection - Commercial</b>	John Borns	Partial	Friday, September 01, 2017
Partial Correction 1 Misc		OK TO COVER CORRIDOR WALLS AND CEILINGS AT: LINK CORRIDOR A111; NW CORRIDOR; CORR 305; CORR LVL 4;	
Partial Correction 2 Misc		OK TO COVER WHEN READY WALL AND CEILING FRAMING + SYSTEMS TO BE ENCLOSED AT: 2ND FLOOR UNITS/SPACES: 203; 204; 232; 233;	

**CODES ADMINISTRATION**

3RD FLOOR UNITS/SPACES: UNITS 303, 304, 332, 333;

4TH FLOOR UNITS/SPACES: 403; 404; 432; 433;

OK FOR 5/8" TYPE X GWB AT WALL ABOVE CEILING AT BACKSIDE  
OF STAIRWELL AT 303, 304, 332;

Partial Correction

3            Misc

FRAMING & ENCLOSED SYSTEMS OK TO COVER AT SHOWER/TUB  
PRE-ROCK LOCATIONS AT: 201; 301; 401; 234; 334; 434; [217; 218;  
221; 222; 225; 226; 227; 228; **[217; 218;**

**Comments:**