

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161750, Building Permit - Commercial

Address: 783 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Monday, September 11, 2017

Partial Correction

1 Misc

OK TO COVER WHEN READY COMPONENTS OF 5/8" TYPE X MOLD-TOUGH GWB RATED ASSEMBLIES AT STAIRWELLS:
NORTH STAIRWELL:
BASEMENT LEVEL 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS

FIRST FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS;

SECOND FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS

THIRD FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS

SOUTH STAIRWELL:

FIRST FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS;

SECOND FLOOR: 1ST & 2ND LAYERS @ WELL FACE + PRE-ROCK AT JOIST BAYS

THIRD FLOOR: 1ST LAYER @ WELL FACE + PRE-ROCK AT JOIST BAYS

Partial Correction

2 Misc

OK TO COVER WHEN READY COMPONENTS OF 5/8" TYPE X MOLD-TOUGH GWB RATED ASSEMBLIES AT ELEVATOR:
2ND FLOOR: 1ST & 2ND LAYERS PRE-ROCK;

Partial Correction
3 Misc

3RD FLOOR: 1ST LAYER PRE-ROCK;

**OK TO COVER WHEN READY 5/8" TYPE X GWB PRE-ROCK AT
SHOWERS:
4TH FLOOR
3RD FLOOR
2ND FLOOR**

**Rough Framing
Inspection -
Commercial**

John Borns

Partial

Monday, September 11, 2017

Partial Correction
1 Misc

OK TO COVER WHEN READY SHEAR WALLS AT:
SOUTH STAIRWELL: BASEMENT
NORTH STAIRWELL: BASEMENT
1ST FLOOR AT SHOWERS & STAIRWELLS

Partial Correction
2 Misc

PRELIMINARY FRAMING INSPECTION AT: 4TH FLOOR; 3RD FLOOR;
2ND FLR; 1ST FLR; BASEMENT

Partial Correction
3 Misc

ROOF SHEATHING NAILED IN PLACE;
EXTERIOR WALL SHEATHING NAILING APPROVED FULL HEIGHT

Comments: