

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20173028, Building Permit - Residential

Address: 4069 NE CHAPEL MANOR DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underslab Plumbing Inspection - Residential	Khanh Nguyen	Failed	Monday, October 16, 2017

Corrective Action Required

1	Misc	**DENIED INSPECTION DUE TO LACK OF EROSION CONTROL
---	------	--

Erosion Control	Khanh Nguyen	Failed	Monday, October 16, 2017
------------------------	--------------	--------	--------------------------

Corrective Action Required

1	DCM1 Erosion Control	EROSION CONTROL REQUIRED ALL AROUND LOT, INCLUDING DISTURBED SOIL/DIRT PILE. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.
---	----------------------	---

Comments: