Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161765, Building Permit - Commercial Address: 801 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Wednesday, October 18, 2017
Partial Correction 1 Misc		OK TO COVER RATED AS	SEMBLIES AT STAIRWELLS:
		SOUTH STAIRWELL: FIRST FLOOR 1ST & 2ND INCLUDING PRE-ROCK A	LAYERS 5/8" TYPE X MOLD-TOUGH GWB T TRUSS-JOIST BAYS;
		INCLUDING PRE-ROCK A	YER 5/8" TYPE X MOLD-TOUGH GWB T TRUSS-JOIST BAYS; 2ND LAYER 5/8" ROCK AT TRUSS-JOIST BAYS;
			R 5/8" TYPE X MOLD-TOUGH GWB .T TRUSS-JOIST BAYS; [2ND LAYER 5/8" USS-JOIST BAYS;
		NORTH STAIRWELL: FIRST FLOOR 1ST & 2ND INCLUDING PRE-ROCK A	LAYERS 5/8" TYPE X MOLD-TOUGH GWB T TRUSS-JOIST BAYS;
		INCLUDING PRE-ROCK A	YER 5/8" TYPE X MOLD-TOUGH GWB T TRUSS-JOIST BAYS; 2ND LAYER 5/8" ROCK AT TRUSS-JOIST BAYS;
			R 5/8" TYPE X MOLD-TOUGH GWB T TRUSS-JOIST BAYS; [2ND LAYER 5/8" AT TRUSS-JOIST BAYS;
Partial Correction		4TH FLOOR -STAIRS 1ST	LAYER

2	Misc	OK TO COVER RATED ASSEMBLIES PRE-ROCK AT ELEVATOR SHAFT:	
		FIRST FLOOR: 1ST & 2ND LAYERS PRE-ROCK AT TRUSS-JOIST BAYS;	
		SECOND FLOOR: 1ST LAYER PRE-ROCK AT TRUSS-JOIST BAYS; 2ND LAYER 5/8" TYPE X PRE-ROCK AT TRUSS-JOIST BAYS;	
		THIRD FLOOR: 1ST LAYER PRE-ROCK AT TRUSS-JOIST BAYS;	
Partial Co	prrection		
3	Misc	OK TO TAPE, MUD, AND FIRESTOP 5/8" TYPE X PRE-ROCK GWB AT TUB/SHOWER WALLS AT: 4TH FLOOR 3RD FLOOR	
		2ND FLOOR	
		1ST FLOOR	
		2ND-LAYERS:	
		2ND - [1ST FLR @ UNIT SIDE CORR & STAIRWELL WALLS	
		2ND -4TH FLOOR	
Partial Co	orrection		
4	Misc	OK TO COVER WHEN READY 5/8" TYPE X GWB AT CEILINGS AND	
		WALLS AT: 1ST FLOOR IT ROOM 1ST LAYER:	

Comments: