

# Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #:PRCOM20161180, Building Permit - Commercial

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK AVE, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	John Borns	Partial	Thursday, October 19, 2017

### Partial Correction

1	Misc	OK TO COVER CORRIDOR WALLS AND CEILINGS AT: LINK CORRIDOR A111; NW CORRIDOR; CORR 305; CORR LVL 4; CORR 219; CORR 307/319;
---	------	--

### Partial Correction

2	Misc	<p>OK TO COVER WHEN READY WALL AND CEILING FRAMING + SYSTEMS TO BE ENCLOSED AT:</p> <p>1ST FLOOR SPACES: 108; 109;</p> <p>2ND FLOOR UNITS/SPACES: 201; 203; 204; 207; 208; 209; 212; 213; 214; 216; 217*; 218*; 219; 232; 233; ABOVE CEILING AT STAIRWELL COMMON WALL AT 201 &amp; 222; 221*; 222*; 224; 225*; 226*; 227*; 228*; 229; 232; 234; [206;</p> <p>3RD FLOOR UNITS/SPACES: 301; 303, 304, 306; 308; 307; 309; 318; 321; 322; 325; 326; 332, 333; 334; [327; 328;</p> <p>4TH FLOOR UNITS/SPACES: 403; 404; 432; 433;</p> <p>OK FOR 5/8" TYPE X GWB AT WALL ABOVE CEILING AT BACKSIDE OF STAIRWELL AT 303, 304, 332;</p>
---	------	--

\*: FLOORS TO BE CORED FOR PLUMBING CORRECTIONS AT SHOWER PANS+

### Partial Correction

3	Misc	FRAMING & ENCLOSED SYSTEMS OK TO COVER AT SHOWER/TUB PRE-ROCK LOCATIONS AT:
---	------	---

201; 206; 208; 217; 218; 221; 222; 225; 226; 227; 228; 234;

301; 306; 308; 318; 321; 322; 325; 326; 327; 328; 334;

401; 406; 408; 418; 421; 422; 425; 426; 427; 428; 434;

506; 508; 517/518; 521; 522; 525; 526; 527; 528;

**Rated Assembly  
Inspection**

John Borns

Partial

Thursday, October 19, 2017

Partial Correction

1 Misc

OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT CEILING  
AND WALLS AT:

LINK CORRIDOR A111 SOUTH 36' + "B"-TO-COMMONS LINK;  
CORR 205 WALLS + LID; CORR A-305 LID & WALLS; CORR 405;  
CORR 219; [CORR 207; LOBBY 205; CORR 219; LOBBY 224;

UNITS: 201; 203; 204; 217; 218; 221; 222; 225; 226; 227; 228; 232;  
233; 234; [209; 210; 212; 229; 231;

UNITS: 303; 304; 332; 333;

UNITS: 403; 404; 432; 433;

ABOVE CEILING AT BACKSIDE OF STAIRWELL WALL AT: 201; 222;  
301; 322; 206;

Partial Correction

2 Misc

OK TO TAPE, MUD, AND FIRE-STOP PRE-ROCK AT SHOWERS/TUBS  
AT:

201; 203; 204; 217; 218; 221; 222; 225; 226; 227; 228; 232; 233;  
234; [206;

301; 303; 304; 318; 321; 322; 325; 326; 327; 328; 332; 333; 334;  
[306; 308;

401; 403; 404; 418; 421; 422; 425; 426; 427; 428; 432; 433; 434;  
406; 408;

**Comments:**