Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171753, Building Permit - Residential Address: 1824 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Friday, October 20, 2017
Corrective Action Required 1 Misc 1. ROOF: Missing ridge and purlin supports over the south bedroom. *Builder reportedly changed this to a vaulted ce submit revised plans or letter approving framing as-constr OK to insulate.			anged this to a vaulted ceiling -

Comments: