

CODES ADMINISTRATION

## **Temporary** Certificate of Occupancy

Permit #:	PRCOM20161758
Address:	789 NW DONOVAN RD, LEES SUMMIT, MO 64086
Inspected On:	Monday, October 23, 2017
Inspected By:	John Borns
Expiration Date:	11/9/2017 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.** 

Inspect	ion:	Inspector:	Outcome:	Date:	
Occupancy Inspection - Codes Commercial		John Borns	Temporary C of O	Monday, October 23, 2017	
Corrective Action Required:					
2	Misc	GUTTERS AND DOWNSPOUTS TO BE INSTALLED AT EAST SIDE			
Corrective Action Required:					
3	Misc	BOLLARD LIGHTS TO BE INSTALLED AT FRONT			
Corrective Action Required:					
4	Misc	ABANDONED WATER PIPING AT POOL EQUIPMENT ROOM TO BE REMOVED			
Corrective Action Required:					

7 Misc PARKING LOT LIGHTS TO BE INSTALLED