

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20171570, Public Works Infrastructure Permit - Commercial
Control Services Company
Address: 3621 NE AKIN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Matt Munger	Partial	Thursday, October 26, 2017

Corrective Action Required

1 Matt Munger 10/06/2017 2:23 PM Your project is in violation of the Erosion and Sediment control policy.

The silt fence is down in several areas around the property and erosion control devices need to be in place around storm inlets.

Informational

2 Matt Munger 10/17/2017 3:47 PM Walked the site to make sure the storm inlets had ESC. Two of the inlets on the south side do not have any protection. The north side of the site needs to have a silt fence put in place.

Informational

3 Matt Munger 10/26/2017 2:17 PM Inlets had erosion control devices in place.

Comments: