

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20171746, Public Works Infrastructure Permit - Residential
Manor at Stoney Creek 2nd - street, storm, sewer and water

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Sanitary Sewer Construction Inspection	Brice Lawson	Partial	Wednesday, November 22, 2017

Informational

- 1 Brice Lawson 11/22/2017 6:18 AM
On 11/21/17 Redford replaced a broken 45 degree bend at the connection to the wye fitting on the sewer lateral for lot 65. The broken 45 degree bend was located due to a leak that was noticed during the air pressure test.

Comments: