

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20161750, Building Permit - Commercial Address: 783 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Concrete Walls and John Borns Passed Wednesday, December 13,

Columns Inspection 2017

Comments: OK TO CLOSE FORMS AND POUR WHEN READY WALL AT MONUMENT SIGN.