

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

| Permit #: PRPWFC20171319, Public Works Infrastructure Perr | nit - Commercial |
|--|------------------|
|--|------------------|

LBP V-A

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection Item: Inspection: | Inspector: | Outcome: | Date: |
|------------------------------|---------------|----------|--------------------------------|
| DEI-Site Visit | Steve Robbins | Partial | Friday, January 05, 2018 |

Corrective Action Required

1 We found water by the main that still needs to be chlorinated, MODOT has a fireline leak and filled up the hole. I talked with Keith and he is going to pump out the water and cover the line with some more straw. Steve Robbins 01/03/2018 10:27 AM

Informational

I checked the erosion control and the silt fence in down, Nick, Matt and Troy have all asked to have the silt fence put back up and it has yet to happen. I sent Scott Ficsher and e-mail this morning asking him to get this taken care of by January 11.Steve Robbins 01/05/2018 1:34 PM

Comments: