Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20172813, Building Permit - Residential Address: 4015 SW MERITAGE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Mike Copeland Not Ready Tuesday, January 09, 2018

Residential

Corrective Action Required

1 Misc **NO ACCESS 2ND INSPECTION, LOCKED***

-STRAP GARAGE PORTAL PER PLANS

- -FUR OUT RETURN AIR TO ACCOMOATE REQUIRED INSULATION.
- -BOCA PLATE PLUMBING 2ND FLOOR BATH TOP PLATE
- -RAFTERS OVER 1ST FLOOR BATH/CLOSET ARE OVERSPAN,

INSTALL PURLIN.

-2-2x12 OVER LIVING CARRYING ROOF LOAD IS OVERSPAN AND NOT ON THE PLAN. HAVE ENGINEER ADDRESS THE BEAM SIZE

OR INSTALL ROOF SUPPORT PER PLAN.

-SHORT WALL OVER 3 LVL, HAVE ENGINEER ADDRESS OR SOLID

BLOCK TO PREVENT LATERAL MOMENT

-INSTALL SECURITY BLOCKING FOR WALKOUT DOOR.
-SOLID BLOCK CANTILEVER FLOOR JOISTS FIREPLACE
-JOIST HANGER DOUBLE JOIST ABOVE BASEMENT STAIRS

Comments: