

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20171420, Public Works Infrastructure Permit - Residential
CREEKSIDE AT RAINTREE

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Brice Lawson	Partial	Friday, January 19, 2018

Partial Correction

- 1 There are problems with the erosion control devices on your site.

Brice Lawson 01/09/2018 11:52 AM

Repair/replace the damaged silt fence on the east side of the site. Install larger rock at the construction entrance. Remove all mud and debris that gets tracked onto the street from this site.

Partial Correction--Brice Lawson 01/19/2018 3:07 PM

A construction entrance has been installed with larger rock.

Corrective Action Required

- 2 Brice Lawson 01/19/2018 3:09 PM

Rock and mud has been tracked onto the street. Remove the rock and mud from the street.

Traffic in and out of this site should use the construction entrance to eliminate/reduce the rock and mud being tracked onto the street.

Comments: