Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161767, Building Permit - Commercial Address: 813 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Friday, January 26, 2018

Inspection

Partial Correction

Misc OK TO COVER WHEN READY 5/8" TYPE X GWB AT:

SOUTH STAIRWELL:

1ST FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; 2ND LAYER

AT WELL FACE AND PRE-ROCK;

2ND FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; PRE-ROCK

ONLY 2ND LAYER; 2ND LAYER WELL FACE;

3RD FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; 2ND LAYER

PRE-ROCK ONLY; 2ND LAYER AT WELL FACE AND PRE-ROCK;

4TH FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; 2ND LAYER

AT WELL FACE;

TOWER: 1ST & 2ND LAYER AT WELL FACE WALLS +LID; 3RD LAYER + HAT CHANNEL AT LID; 4TH LAYER AT LID; 1ST LAYER LOWER CEILINGS AT LANDING; 2ND LAYER LOWER CEILINGS AT LANDING; 3RD LAYER + HAT CHANNEL @ LOWER CEILINGS AT LANDING;

4TH LAYER @ LOWER CEILINGS AT LANDING

NORTH STAIRWELL:

1ST FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; 2ND LAYER

AT WELL FACE AND PRE-ROCK;

2ND FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; PRE-ROCK

ONLY 2ND LAYER; 2ND LAYER WELL FACE;

3RD FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; 2ND LAYER

PRE-ROCK ONLY; 2ND LAYER AT WELL FACE AND PRE-ROCK;

4TH FLOOR: 1ST LAYER AT WELL FACE AND PRE-ROCK; 2ND LAYER

AT WELL FACE;

TOWER: 1ST & 2ND LAYER AT WELL FACE WALLS +LID; 3RD LAYER + HAT CHANNEL AT LID; 4TH LAYER AT LID; 1ST LAYER LOWER CEILINGS AT LANDING; 2ND LAYER LOWER CEILINGS AT LANDING;

3RD LAYER + HAT CHANNEL @ LOWER CEILINGS AT LANDING;

4TH LAYER @ LOWER CEILINGS AT LANDING

Partial Correction

2 Misc OK TO COVER WHEN READY 5/8" TYPE X GWB AT ELEVATOR

1ST FLOOR: 1ST LAYER PRE-ROCK; 2ND LAYER PRE-ROCK; 2ND FLOOR: 1ST LAYER PRE-ROCK; PRE-ROCK 2ND LAYER; 3RD FLOOR: 1ST LAYER PRE-ROCK; 2ND LAYER PRE-ROCK;

SHAFT FACE: 1ST LAYER AT WALLS + LID; 2ND LAYER AT WALLS +

LID; 3RD LAYER + HAT CHANNEL AT LID; 4TH LAYER AT LID

Partial Correction

3 Misc OK TO COVER WHEN READY 5/8" TYPE X:

BEHIND TUBS/SHOWERS ADJACENT TO STAIRWELLS AT:

4TH FLOOR: 1ST LAYER; 2ND LAYER 3RD FLOOR: 1ST LAYER; 2ND LAYER 2ND FLOOR: 1ST LAYER; 2ND LAYER 1ST FLOOR: 1ST LAYER; 2ND LAYER

SHEAR WALLS:

1ST FLOOR: 1ST LAYER @ IT ROOM; 1ST LAYER AT SHEAR WALLS +

2ND LAYER @ IT ROOM; 2ND LAYER AT SHEAR WALLS 2ND FLOOR: 1ST LAYER AT SHEAR WALLS AT STAIRWELLS & ELEVATOR IN CORRIDOR & UNITS; 2ND LAYER AT SHEAR WALLS

AT STAIRWELLS & ELEVATOR IN CORRIDOR & UNITS;

3RD FLOOR: 1ST LAYER AT SHEAR WALLS AT STAIRWELLS &

ELEVATOR IN CORRIDOR & UNITS;

4TH FLOOR: 1ST LAYER AT SHEAR WALLS AT STAIRWELLS &

ELEVATOR IN CORRIDOR & UNITS;

Partial Correction

4 Misc 5/8" TYPE X GWB OK TO COVER AT CEILINGS & WALLS AT:

4TH FLOOR CEILINGS & WALLS COMPLETE INCLUDING 2ND LAYER

AT SHEAR WALLS AT STAIRWELLS & ELEVATOR SHAFT ON

UNIT/CORRIDOR FACE;

3RD FLOOR CEILINGS & WALLS COMPLETE INCLUDING 2ND LAYER

AT SHEAR WALLS;

2ND FLOOR CEILINGS & WALLS COMPLETE INCLUDING 2ND

LAYER AT SHEAR WALLS;

Partial Correction

5 Misc -1ST FLOOR SHEAR WALL-OK

-1ST FLOOR ELEVATOR MACHINE RM: [CEILING TWO LAYERS

Friday, January 26, 2018

All Rough Inspection - John Borns Partial

Commercial

Partial Correction

L Misc OK TO COVER WHE READY FRAMING AND CONCEALED SYSTEMS

AT:

4TH FLOOR; 3RD FLOOR; 1ST FLOOR INCLUDING FRAMING +

M/E/P;

Partial Correction

2 Misc OK TO COVER WHEN READY RC CHANNEL AT CEILINGS & WALLS

AT:

4TH FLOOR; 3RD FLOOR; 2ND FLOOR;

[1ST FLOOR COMPLETE INCLUDING GARAGE CEILINGS

Comments: