Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161769, Building Permit - Commercial Address: 825 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
hispection.	mspector.	outcome.	bute.
Rated Assembly Inspection	John Borns	Partial	Monday, February 12, 2018
Partial Correction			
1 Misc		OK TO COVER WHEN READY 5/8"	TYPE X GWB AT STAIRWELLS:
		EAST STAIRWELL: LST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY; 2ND LAYER WALLS ONLY; 2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK; 3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS LST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER; 4TH FLOOR: STAIRWELL FACE SIDE WALLS COMMON WITH UNITS LST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER; 4TH FLOOR: STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER; 4TH FLOOR: STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER; 5OWER ABOVE 4TH FLOOR: 1ST LAYER AT CEILING & WALLS; 2ND AYER AT CEILING & WALLS; [4TH LAYER AT HIGH CEILING; 2ND AYER AT LOWER CEILINGS;	
		WEST STAIRWELL: 1ST FLOOR: 1ST LAYER INCLUDIN PRE-ROCK ONLY; 2ND LAYER WAI 2ND FLOOR: 1ST LAYER INCLUDIN PRE-ROCK; 3RD FLOOR: 1ST LAYER INCLUDIN STAIRWELL FACE SIDE WALLS CO STAIRWELL FACE SIDE WALLS CO 4TH FLOOR: STAIRWELL FACE SID 1ST LAYER; STAIRWELL FACE SID	LS ONLY; IG PRE-ROCK; 2ND LAYER G PRE-ROCK; MMON WITH UNITS 1ST LAYER; MMON WITH UNITS 2ND LAYER; E WALLS COMMON WITH UNITS

		2ND LAYER; TOWER ABOVE 4TH FLOOR: 1ST LAYER AT CEILING & WALLS; 2ND LAYER AT CEILING & WALLS; [4TH LAYER AT HIGH CEILING; 2ND LAYER AT LOWER CEILINGS;
Partial Cor	rrection	
2 N	Misc	ELEVATOR SHAFT:
		1ST FLOOR: 1ST LAYER PRE-ROCK; 2ND LAYER PRE-ROCK
		2ND FLOOR: 1ST LAYER PRE-ROCK;
		3RD FLOOR: 1ST LAYER PRE-ROCK;2ND LAYER PREROCK
Partial Cor	rrection	
3 Misc	Misc	OK TO COVER WHEN READY 5/8" TYPE X GWB:
		4TH FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;
		[LOCATIONS FOR SOFFITS & DROP CEILINGS;
		3RD FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;
		2ND FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;
		1ST FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;

All Rough Inspection - Commercial	John Borns	Not Ready	Monday, February 12, 2018
Partial Correction			
1 Misc		OK TO COVER WHEN READY AT:	FRAMING AND ENCLOSED SYSTEMS
			: #4, 3, 2, 1; BEHIND SHOWERS AT OWER CEILING & WALLS ABOVE 4TH
		ELEVATOR SHAFT OK TO COVER AT: [4TH FLOOR;	
		4TH FLOOR CEILINGS & WAI COMPLETE;	LLS OK TO COVER; RC CHANNEL
		[3RD FLOOR CEILINGS & WA	ALLS OK TO COVER;
		1ST FLOOR: WALL CAVITIES	AT SHEAR WALLS OK TO COVER;
Comments:			

Comments: