

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFR20171746, Public Works Infrastructure Permit - Residential  
Manor at Stoney Creek 2nd - street, storm, sewer and water

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Jeremy Young	Partial	Tuesday, February 13, 2018

Informational

- 1 Jeremy Young 02/13/2018 1:57 PM It appears all silt fencing is intact and in place for ESC. The east side of the project has had straw placed for soil stabilization. The west side of the project has bales of straw ready for placement.

Comments: