## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20161769, Building Permit - Commercial Address: 825 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Wednesday, February 14, 2018
Inspection

Partial Correction

1 Misc OK TO COVER WHEN READY 5/8" TYPE X GWB AT STAIRWELLS:

**EAST STAIRWELL:** 

1ST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER

PRE-ROCK ONLY; 2ND LAYER WALLS ONLY;

2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER

PRE-ROCK;

3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER

PRE-ROCK; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS

2ND LAYER;

4TH FLOOR: STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS

2ND LAYER;

TOWER ABOVE 4TH FLOOR: 1ST LAYER AT CEILING & WALLS; 2ND LAYER AT CEILING & WALLS; 4TH LAYER AT HIGH CEILING; 2ND LAYER AT LOWER CEILINGS; 2ND LAYER AT WALLS; 3RD LAYER + HAT CHANNEL @ LOWER CEILINGS; [4TH LAYER @ LOWER CEILINGS;

WEST STAIRWELL:

1ST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER

PRE-ROCK ONLY; 2ND LAYER WALLS ONLY;

2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER

PRE-ROCK;

3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK;

STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER;

4TH FLOOR: STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 1ST LAYER; STAIRWELL FACE SIDE WALLS COMMON WITH UNITS 2ND LAYER

2ND LAYER;

TOWER ABOVE 4TH FLOOR: 1ST LAYER AT CEILING & WALLS; 2ND LAYER AT CEILING & WALLS; 4TH LAYER AT HIGH CEILING; 2ND LAYER AT LOWER CEILINGS; 2ND LAYER AT WALLS; 3RD LAYER + HAT CHANNEL @ LOWER CEILINGS; [4TH LAYER @ LOWER CEILINGS;

**Partial Correction** 

2 Misc

**ELEVATOR SHAFT:** 

1ST FLOOR: 1ST LAYER PRE-ROCK; 2ND LAYER PRE-ROCK

2ND FLOOR: 1ST LAYER PRE-ROCK;

3RD FLOOR: 1ST LAYER PRE-ROCK;2ND LAYER PRE-ROCK

SHAFT INNER FACE: 1ST LAYER FULL HEIGHT;

SHAFT CEILING: 1ST LAYER; [2ND LAYER;

**Partial Correction** 

3 Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB:

4TH FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER; LOCATIONS FOR SOFFITS & DROP CEILINGS; CEILINGS AND WALLS THROUGHOUT, INCLUDING 2ND LAYER AT STAIRWELLS &

**ELEVATOR SHAFT**;

3RD FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;

2ND FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;

1ST FLOOR: BEHIND TUBS/SHOWERS 1ST LAYER, 2ND LAYER;

All Rough Inspection - John Borns
Commercial

Partial

Wednesday, February 14, 2018

**Partial Correction** 

1 Misc

OK TO COVER WHEN READY FRAMING AND ENCLOSED SYSTEMS

AT:

SHOWER WALLS AT FLOORS: #4, 3, 2, 1; BEHIND SHOWERS AT 4TH & 3RD FLOORS; STAIR TOWER CEILING & WALLS ABOVE 4TH

FLOOR;

**ELEVATOR SHAFT OK TO COVER AT:** 

4TH FLOOR;

4TH FLOOR CEILINGS & WALLS OK TO COVER; RC CHANNEL

COMPLETE;

3RD FLOOR CEILINGS & WALLS OK TO COVER; [RC CHANNEL COMPLETE;

2ND FLOOR CEILINGS & WALLS OK TO COVER;

1ST FLOOR: WALL CAVITIES AT SHEAR WALLS OK TO COVER;

**Comments:**