

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20173801, Public Works Infrastructure Permit - Commercial

Residences at Echelon

Address: 3500 SW HOLLYWOOD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Sanitary Sewer - Invert	Matt Munger	Partial	Friday, February 16, 2018

Informational

- 1 I came by this morning and talked with Daniel. They finished pouring the inverts for sanitary MH a-3 and a-4. I was not able to get back out in the afternoon, but jeremy and John went out for me in the afternoon. Steve Robbins 02/09/2018 3:44 PM

Informational

- 2 Matt Munger 02/14/2018 9:57 AM I opened up MH A-3 and A-4 and observed the inverts that had been poured. The inverts were smooth and flowed in the proper direction.

Informational

- 3 Matt Munger 02/15/2018 3:06 PM
Opened up manholes B-1, B-2, B-3 and C-1. All inverts were smooth and formed correctly.

I did see something in B-2 that I will have another inspector look at, at a later time. The invert at the upstream pipe looks as if there is a little bit of water sitting. Will return to do a follow up inspection to see if there is an issue.

Corrective Action Required

- 4 Matt Munger 02/16/2018 9:50 AM
Tom C. and I looked at MH B-2 to double check the area that I was concerned about. Tom thought maybe the invert could be ground down a bit to avoid holding water.

Comments: