
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20172142, Building Permit - Residential

Address: 1615 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Matt Munger	Failed	Tuesday, February 20, 2018

Corrective Action Required

- 1 Matt Munger 02/20/2018 9:38 AM
Due to the weather I informed the contractor (left voicemail) that he will need to call back for an inspection another day to ensure proper compaction.

Comments:
