

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20162552, Public Works Infrastructure Permit - Commercial SUMMIT SQUARE APPARTMENTS

Address: 801 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection Item: Inspection: | Inspector: | Outcome: | Date: |
|---|---------------|----------|----------------------------------|
| DEI-Erosion Sediment Control (ESC) Inspection | Steve Robbins | Failed | Tuesday, February 20, 2018 |

Informational

- 1 The erosion control is in good condition and has no problems at this time. Informational
- 2 The erosion control is in place. There are no issues at this time.

Informational

- 3 The erosion control is in place. Steve Robbins 12/27/2017 1:32 PM Informational
- The erosion control behind the buildings is in place and seems to be working. Steve Robbins 01/19/2018 2:18 PM

Informational

The erosion control is in place, they are using mulch berms instead of silt fence. Everything looks good. Steve Robbins 02/01/2018 1:45 PM

Corrective Action Required

There is some run-off by building 6, I talked with Jonathon Myers and they will get some silt fence up as soon as the weather lets up in the next day or so. Steve Robbins 02/20/2018 11:04 AM

Comments: