

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20171319, Public Works Infrastructure Permit - Commercial
LBP V-A

Address: 2900 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Steve Robbins	Failed	Wednesday, February 21, 2018

Corrective Action Required

- 1 There are problems with the erosion control devices on your site. The silt fence in front of and around the building has fallen down. I called Scott Fischer and let him know that the fence needs to get back up, he said he would take care of it. I am giving them to March 2, 2018 to get it up because the ground is frozen. Steve Robbins 02/21/2018 11:50 AM

Comments: