## **CODES ADMINISTRATION**

## Temporary Certificate of Occupancy

Permit #: PRCOM20161180

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK

**AVE, LEES SUMMIT, MO 64081** 

Inspected On: Tuesday, March 13, 2018

**Inspected By:** John Borns

Expiration Date: 3/29/2018 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.** 

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Tuesday, March 13,

Codes Commercial 2018

Corrective Action Required:

1 Misc CODES ISSUES AT BUILDING EXTERIOR & SITE:

- SPACE UNDER EAST WALL OF A-B LINK?

- CUT SANITARY CLEANOUT RISERS TO GRADE; CAP
- UNFINISHED MASONRY AT EXTERIOR WALLS
- SPLASH BLOCKS OR EQUIVALENT EROSION CONTROL REQUIRED

AT BOTTOMS OF DOWNSPOUTS

- REPAIR/REPLACE DAMAGED SHROUDS AT BASES OF LIGHT POLES;

CLOSE WIRING ACCESS OPENINGS

- SEAL ALL PENETRATIONS OF BLDG EXTERIOR WALLS
- PAINT EXPOSED STEEL GAS PIPE
- SECURE CONDENSER ELECTRICAL WHIPS TO WALLS WITHIN 12"
  OF DISCONNECTS AND WHERE NEEDED TO PREVENT GROUND

CONTACT.

## Corrective Action Required:

2 Misc CODES ISSUES WITHIN PARKING GARAGE:

- LOOSE ELECT RECEPT EAST OF DOOR A107A

- ENSURE ALL OPENINGS IN SUSPENDED CONCRETE DECK ABOVE

ARE FIRE-STOPPED

Corrective Action Required:

3 OTHER DEPARTMENT ISSUES TO BE RESOLVED:

FIRE DEPARTMENTFIELD ENGINEERING

- PLANNING

TEMPORARY OCCUPANCY CERTIFICATE EXTENDED TO ABOVE DATE TO ACCOMODATE RESOLUTION OF FIRE DEPARTMENT ISSUES. CONTACT CPT WEISSENBACH DIRECTLY.

CALL 816-969-1200 TO REQUEST RE-INSPECTION OF CODES ISSUES WHEN READY.

WHEN FINISH SITEWORK IS COMPLETED AND READY FOR INSPECTION CONTACT:

- BOB BURNS @ 816-969-1838 FOR FINAL INSPECTION OF FIELD ENGINEERING COMPONENTS
- CHRISTINA STANTON @ 816-969-1607 FOR FINAL INSPECTION OF PLANNING COMPONENTS