

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180158, Development - Subdivision
Park Ridge 6th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Jeremy Young	Partial	Monday, March 19, 2018

Informational

1 Jeremy Young 02/27/2018 1:16 PM Spoke with contractor about ESC devices. The contractor has installed silt fencing around the perimeter of the site. The contractor will also be mulching trees and using the mulch for ESC in other areas of the site.

Informational

2 Jeremy Young 03/08/2018 11:19 AM Contractor is working to complete the ESC as called out in plans. They have removed and ground trees for mulch that will be used for ESC. The contractor will take what precautions are needed for the detention basin. Will re-inspect.

Informational

3 Jeremy Young 03/19/2018 11:19 AM We have had approximately 1-2" of rain this morning. All ESC devices are intact and working properly. Small amounts of sediment are leaving the site.

Comments: