

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #: PRPWFC20162552, Public Works Infrastructure Permit - Commercial

**SUMMIT SQUARE APPARTMENTS** 

Address: 801 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection Item: Inspection:                  | Inspector:    | Outcome: | Date:                        |
|---|---------------|----------|------------------------------|
| DEI-Erosion Sediment Control (ESC) Inspection | Steve Robbins | Failed   | Monday,<br>March 26,<br>2018 |

## Informational

There are problems with the erosion control devices on your site. I talked with Jonathan from Emery Sapp about the run-off coming down the north side to the parking lot. They installed alot of silt fence to try and correct this, but it did not work. Jonathan said they are going to move some dirt around and try to change the grade to try and divert the water run-off. Steve Robbins 03/26/2018 2:28 PM

## **Comments:**