
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20171839, Building Permit - Residential

Address: 4012 SW MERITAGE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Matt Munger	Failed	Tuesday, March 27, 2018

Corrective Action Required

- 1 Matt Munger 03/27/2018 11:46 AM
ESC devices need to be installed on the property to prevent silt from leaving the site. Silt has gotten into the curb gutter and will need to be removed. A Stop Work Order may be issued if ESC is not in compliance.

Comments:
