

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRRES20172815, Building Permit - Residential

Address: 1813 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

**Inspection Item:**

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
Driveway Inspection	Tom Chandler	Failed	Thursday, April 05, 2018

Informational

1 Tom Chandler 03/22/2018 1:19 PM Inspected forms and compacted aggregate only.

Corrective Action Required

2 Tom Chandler 04/05/2018 2:01 PM Driveway approach does not meet ADA cross slope requirements.

DEI-Sidewalk Inspection	Tom Chandler	Failed	Thursday, April 05, 2018
-------------------------	--------------	--------	-----------------------------

Corrective Action Required

1 The sidewalk does not meet ADA guidelines.  
Tom Chandler 04/05/2018 2:08 PM Sidewalk on the west side of the driveway needs corrected.

**Comments:**