

Temporary Certificate of Occupancy

Permit #: PRCOM20161765
Address: 801 NW DONOVAN RD, LEES SUMMIT, MO 64086
Inspected On: Thursday, April 19, 2018
Inspected By: John Borns
Expiration Date: 5/3/2018 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Temporary C of O	Thursday, April 19, 2018

Corrective Action Required:

1	Misc	ENSURE ALL ROOF MEMBRANE OPENINGS ARE SEALED -- SEE AT ELEVATOR AND STAIRWELL "DOGHOUSES"
---	------	---

Corrective Action Required:

2	Misc	IBC 1009.10 REQUIRED HANDRAILS AT COMMERCIAL STAIR: REQUIRED BOTH SIDES OF STAIR. HEIGHT OF HANDRAIL AT STAIR MIN/MAX HEIGHT 34" TO 38" VERTICAL FROM TREAD NOSING. ENDS MUST RETURN TO STRUCTURE. SEE AT ENTRANCE TO SPRINKLER ROOM.
---	------	---

Corrective Action Required:

4	Misc	CONVEY MAIN WATER SERVICE BACKFLOW DEVICE TEST REPORT TO LS WATER DEPT.
---	------	---

Corrective Action Required:

5	Misc	COMPLETE FINISH SITEWORK AND OBTAIN APPROVAL FROM LS PLANNING.
---	------	--

