LEE'S SUMMIT

## PUBLIC WORKS ENGINEERING DIVISION

## **Inspection Summary**

Permit #: PRPWFC20173800, Public Works Infrastructure Permit - Commercial Residences at Echelon

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:				
Inspection:		Inspector:	Outcome:	Date:
DEI-Grading/Excavation/Fill Inspection Informational		Matt Munger	Partial	Friday, April 27, 2018
Contr wall.	actors were wo		retention basin to start we tions will be required for th	•
DEI-Erosion Sec (ESC) Inspectio Informational		Matt Munger	Partial	Friday, April 27, 2018
<ul> <li>Matt Munger 04/05/2018 2:55 PM</li> <li>I walked along the silt fence and I did not see any signs of failure. TJ had silt fence installed on the north end (off-site) where they have disturbed the soil.</li> </ul>				
Informational				
<ul> <li>Matt Munger 04/12/2018 9:28 AM</li> <li>Walked along the silt fence and checked for issues. The silt fence was trenched in properly and I did not observe any areas where silt has gotten past the fence.</li> </ul>				
Informational				
3 Matt Munger 04/20/2018 9:16 AM The silt fence is intact and the construction entrance is in good condition.				
Corrective Action Required				
4 Matt Munger 04/25/2018 2:57 PM Gravel and mud has been tracked onto the street from the traffic going in and out of the site. I sent a message to TJ informing of the issue.				
Informational				

5 Matt Munger 04/27/2018 11:30 AM ESC devices were in place.

**Comments:**