

FIRE DEPARTMENT

PLAN REVIEW CONDITIONS

May 03, 2018

CR ARCHITECTS 750 NORTH SAINT PAUL STREET STE 450 DALLAS , TX 75201

Permit No:	PRCOM20181329
Project Title:	STARBUCKS
Project Address:	1130 NE DOUGLAS ST, LEES SUMMIT, MO 64086
Parcel Number:	5291014080000000
Location:	DOUGLAS STATION COMMERCIAL PARK LOTS 3-A, 4-A & 5-ALOT 3-A
Type of Work:	ALTERATION COMMERCIAL
Occupancy Group:	ASSEMBLY FOR FOOD AND DRINK INC BARS, RESTAURANTS, BANQUET HALLS
Description:	INTERIOR REMODEL OF EXISTING STORE

The following is a list of requirements from the City of Lee's Summit that have not been satisfactorily addressed in the plans and specifications. Please contact the appropriate department regarding clarification of comments.

Development Services Department	(816) 969-1200	Fire Department (816) 969-1300
Building Plan Review	Reviewed By: Joe Frogge	Pending
Fire Plan Review	Reviewed By: Joe Dir	Approved with Conditions

1. 2012 IFC 1004.3- Posting of occupant load. Every room or space that is an assembly occupancy shall have the occupant load of the room or space posted in a conspicuous place, near the main exit or exit access doorway from the room or space. Posted signs shall be of an approved legible permanent design and shall be maintained by the owner or authorized agent.

ACTION REQUIRED: (verified at inspection)

Post the occupant load of 32 on the interior of the sales/seating area close to the entrance.

2. 2012 IFC 505.1- Address numbers. New and existing buildings shall have approved address numbers, building numbers or approved building identification placed in a position that is plainly legible and visible from the street or road fronting the property. These numbers shall contrast with their background. In Multi-tenant commercial building where tenants have multiple entrances located on different sides of the building , each door shall be addressed. Address numbers shall be Arabic numerals or alphabet letters. Numbers shall be a minimum of 4 inches (102 mm) high with a minimum stroke width of 0.5 inch (12.7 mm).

ACTION REQUIRED: (verified at inspection)

The numeric address of 1130 shall be readable from the roadway on both the front and rear door.

3. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed.

ACTION REQUIRED:(veriifed at inspection)

The fire extinguisher shall be up to date with the annual service. A current service tag shall be posted on the fire extinguisher with the last serive date.

4. Health Dept

ACTION REQUIRED: (information purposes)

The Jackson County Health Dept will need to conduct an inspection on the business before opening up for dirve through or walk-in business.

The approval of plans and specifications does not permit the violation of any section of the Building Codes or other City Ordinances or State Law.

The review conducted by the City of Lee's Summit Development Services Department shall not be construed as a structural review of the project.