
PLANNING AND DEVELOPMENT**Final Inspection Report**
Inspection Summary

Permit #: PRCOM20171689, Building Permit - Commercial**Permit Project Title:** SAINT LUKES EAST - OR ADDITION #2**Address:** 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Planning	Hector Soto Jr., Planning Division Manager	Failed	Tuesday, January 23, 2018

Corrective Action Required

1 Parking lot striping shall be completed per the approved plan.

Corrective Action Required

2 Wallpack lighting shall be installed per the approved architectural drawings.

Occupancy Inspection - Planning	Hector Soto Jr., Planning Division Manager	Temporary C of O	Thursday, May 10, 2018
----------------------------------------	-----------------------------------------------	------------------	------------------------

Corrective Action Required

1 Miscellaneous Replace dead tree adjacent to the parking lot entrance.
Correction

Occupancy Inspection - Planning	Hector Soto Jr., Planning Division Manager	Temporary C of O	Thursday, May 10, 2018
----------------------------------------	-----------------------------------------------	------------------	------------------------

Corrective Action Required

1 The dead tree in the landscaping area shall be removed and replaced.

Comments: