

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20162083, Public Works Infrastructure Permit - Commercial

WATER UTILITIES FACILITY

Address: 1200 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|---------------------|--------------|----------|----------------------------|
| DEI-Storm - Rip Rap | Brice Lawson | Partial | Thursday, June 07, 2018 |

Informational

1 Brice Lawson 06/07/2018 1:31 PM

Rip rap sections have been installed above and below the dual culvert pipes located in the northwest corner of the site. It appears small rock is washing into the culvert and the west end of the culvert appears to be partially washed out under the pipe in a small area. I sent an email to Casey Williams and Jeff Thorne to make them aware that these items may potentially cause future maintenance challenges.

| | | | |
|---|--------------|---------|----------------------------|
| DEI-Sanitary Sewer Construction Inspection | Brice Lawson | Partial | Thursday, June 07, 2018 |
|---|--------------|---------|----------------------------|

Informational

1 Brice Lawson 06/07/2018 1:36 PM

While performing a punch list inspection on 6/5, I noticed the existing sanitary manhole frame for manhole 39-184 was shifted off of center of the manhole. I sent an email to Josh Roach and he plans to take care of any needed repairs to the manhole.

Comments: