

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20181678, Building Permit - Residential

Address: 4430 SW AMETHYST DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Brice Lawson	Partial	Monday, June 11, 2018

Corrective Action Required

1 Brice Lawson 06/11/2018 3:43 PM
It appears that a track loader used to dig the foundation for this lot crossed Merryman Rd and caused damage to the public curb near the west property line. Make proper corrections to the curb.

Proper precautions should be met to eliminate the possibility of damaging public infrastructure prior to crossing the street with construction equipment.

This inspection is labeled as a driveway inspection so the FEI will see it when the driveway is inspected and the flatworkers are in the area. A picture of the damaged curb is in documents and images.

Footing Inspection - Residential	John Benisch	Passed	Monday, June 11, 2018
-------------------------------------	--------------	--------	--------------------------

Comments: