

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20171187, Building Permit - Residential

Address: 3400 SW LOIS LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Sidewalk Inspection	Brice Lawson	Failed	Thursday, June 14, 2018

Corrective Action Required

- 1 The sidewalk does not meet ADA guidelines.

Brice Lawson 06/14/2018 3:22 PM
Make proper corrections.

DEI-Driveway Inspection	Brice Lawson	Failed	Thursday, June 14, 2018
-------------------------	--------------	--------	----------------------------

Corrective Action Required

- 1 Matt Munger 04/09/2018 10:42 AM
The sidewalk within the driveway approach did not meet ADA standards. There were several spots that were over 2%. I contacted Carlos and informed him the approach will need to be replaced. I told him to call in for an inspection before they pour the approach.

Comments: