Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20180476, Building Permit - Residential Address: 1345 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Tuesday, June 26, 2018

Residential

Corrective Action Required

1 Misc REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION

CONTROL INSTALLATION ALONG THE STREET. INSTALL GRAVEL AT

LOT ENTRANCE

Erosion Control Khanh Nguyen Failed Tuesday, June 26, 2018

Corrective Action Required

1 DCM5 Erosion Control REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION

CONTROL INSTALLATION ALONG THE STREET. INSTALL GRAVEL AT

LOT ENTRANCE

Comments: