

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20180023, Building Permit - Residential

Address: 408 SE WEISS CIR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	John DiMauro	Failed	Monday, July 02, 2018

Corrective Action Required

1 John DiMauro 07/02/2018 9:53 AM

There are chips along the curb that need to be patched. I informed the contractor to make the corrections before the driveway can be passed.

Comments:
