

FIRE DEPARTMENT

PLANS REVIEW CONDITIONS

Permit No:	PRCOM20173755	Date:	July 26, 2018	
Project Title:	PAPA JOHN'S	Applicant:		
Location:				
	865 SW LEMANS LN, LEES SUMMIT, MO 64082		404 B NW 11TH ST	
Type of Work:		BLUE SPRINGS, MO 64015		
Occupancy Group:		Drimon (81C) 224 2400		
Description: TENANT FINISH FOR CARRY OUT		Primary: (816) 224-3400		
	PIZZA SHOP			
Construction Type: Type VB (Unprotected)				
Map Page:	215A			

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review

Reviewed By: Joe Dir

Released for Construction

1. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed. ACTION REQUIRED:

The existing riser shall be current with all required service and maintenance. A current service tag shall be posted on the riser.

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.