

# Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #:PRRES20180728, Building Permit - Residential  
Address: 1845 SW BLACKSTONE CT, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Gas Piping Inspection - Residential</b>	Jason McRoy	Failed	Wednesday, August 01, 2018

### Corrective Action Required

1	Misc	- NO PSI IN GAS LINE - GAS LINE NOT CONNECTED AT FIRE PLACE
---	------	--

<b>All Rough Inspection - Residential</b>	Jason McRoy	Failed	Wednesday, August 01, 2018
---	-------------	--------	----------------------------

### Corrective Action Required

1	Misc	- nails sticking out of sill plate at stairs - ledger lock or lag ledger board at deck per code - reframe south wall at office per plans for no door - missing stud in closet side of guest bathtub - need anchors 12" from butt ends of sill plate in garage tighten 2 anchors down - cut studs at southwest bed in basement center of windows - complete HVAC duct work in southwest bedroom in basement -
---	------	---

<b>Electrical Service Inspection - Residential</b>	Jason McRoy	Passed	Wednesday, August 01, 2018
--	-------------	--------	----------------------------

<b>Gas Service Inspection -</b>	Jason McRoy	Failed	Wednesday, August 01, 2018
---------------------------------	-------------	--------	----------------------------

**Residential****Corrective Action Required**

1            Misc                            -NO PSI IN GAS LINE

**Comments:**