Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181829, Building Permit - Residential Address: 1325 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Underslab Plumbing Khanh Nguyen Failed Monday, August 20, 2018

Inspection - Residential

Corrective Action Required

1 Misc -VENT BASEMENT BATH TUB/SHOWER

Erosion Control Khanh Nguyen Failed Monday, August 20, 2018

Corrective Action Required

1 DCM2 Erosion Control DEFICIENT EROSION CONTROL INSTALLATION.

EROSION CONTROL SHALL BE INSTALLED ALONG PROPERTY LINES

AND RESTORED ALONG THE STREET

NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL

PROVIDED.

Comments: