## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRRES20181168, Building Permit - Residential Address: 1313 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date: Inspector: All Rough Inspection -Khanh Nguyen Friday, August 24, 2018 Failed Residential Corrective Action Required Misc -2x10 @12" oc above garage per plan -Insulation used as fireblocking material must be min 16" from ceiling level down at master bath shower wall -Install hanger for double joist connection at stair -Toe nail joists to basement sill plates with 3-8d nails -Nail corner studs per code on 2nd fl -Nail wall intersections -Move roof support struts above 2nd fl to bearing wall. NOTE: use the bearing wall at stair \*\*DO NOT INSULATE BASEMENT

**Comments:**