

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20181168, Building Permit - Residential

Address: 1313 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Wednesday, September 05, 2018

Corrective Action Required

1	Misc	-Install hanger for double joist connection at stair. As an alternative, the framer can install Simpson L support brackets on both sides of the double joist
		-Resecure&support wiring above 2nd fl. The framer removed the wiring when relocate theroof supporting struts to the bearing wall
		-Rewire the circuit to garage ceiling garage opener outlet

**OK TO INSULATE

Comments: