Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20182146, Building Permit - Residential Address: 1700 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: All Rough Inspection -Jason McRoy Failed Wednesday, October 10, 2018 Residential Corrective Action Required Misc fire stop at gas line penetration at fireplace Missing 3 joist hangers at girder connection in great room Header and hanger at cut joist in southeast basement Cannot use a 100 psi gauge on gas piping 30psi max * OK TO INSULATE * Wednesday, October 10, 2018 **Gas Service Inspection -** Jason McRoy Failed Residential Corrective Action Required Misc **Gas Piping Inspection** - Jason McRoy Failed Wednesday, October 10, 2018 Residential Corrective Action Required *CANNOT USE 100 PSI GAUGE ON GAS LINE 30 PSI MAX 2 Misc

Comments: