



DEVELOPMENT SERVICES

Inspection Summary

Permit #:PRCOM20180700, Building Permit - Commercial

Address: 217 NW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Footing Inspection - Commercial	Jason McRoy	Failed	Monday, October 22, 2018

Corrective Action Required

1	Misc	- lower west footing.
---	------	-----------------------

Corrective Action Required

2	Misc	BUILDING #4 PERIMETER FOOTING * REMOVE EXCESS WATER IN FOOTING * RAISE CRUSHED CHAIRS TO 3 " * ADD BLOCK OUTS TO SECTION OVER SEWER CONNECTION WHICH WILL NOT BE POURED
---	------	--

Comments: